Component	Module					DVFS 1-1vc 01
Defect	Cell cracl	ks				F VI O 1-105.01
Appearance	Cell cracks cannot be the cracks electrolumi lengths an eye when t the cracks cells which metal finge on cell edg it occurs al small bubb	are cracks in the s seen by the naked of can be seen. Cell inescence, UV fluore d orientations (crack they form snail trac A snail track is a d n occurs typically 3 ers on cells may be s es. Photobleaching long the cracks and les.	ilicon subs eye. Only la cracks can escence or k patterns) ks or wher liscoloratio months to ilver, yellov is a counte the border	trate of the phot arge cracks or w be easily detect lock-in thermog Small cell crac photobleachin n of the silver pa 1 year after inst w or brown in app tracting effect to	ovoltaic cells. there the back cted through in traphy. Cell cra- traphy. Cell cra- trag or delamin aste of the from tallation of the pearance, this the yellowing elamination al	Most of the cell cracks sheet is visible through maging techniques like acks can have different cks) become visible by ation takes place along nt metallisation of solar PV modules. Affected effect can also be seen of the encapsulant and ong cracks is visible as
Detection	EL, UV (IR	T, VI ,IV)				
Origin	Cell cracks operation. Especially production the installa may result ical stresse patterns ca not always failure, who heavy med in all. The and tempe	Cell cracks can have origin in all lifetime phases of a PV module: production, installation and operation. In production, cell cracks can occur during wafer, cell and module manufacturing. Especially the stringing and soldering process of the solar cells can damage the cells. After production, major sources for cell cracks are the packaging and transport of the modules, and the installation. After installation, external forces like hail, heavy snow weight or strong wind may result in cell cracks. Once cell cracks are present, further mechanical and thermomechanical stresses can lead to the propagation of the cracks into longer and wider cracks. Some crack patterns can give indications on the origin of the failure, but the final cause of cell breakage is not always easy to identify. A repetitive crack pattern can be for example caused by a production failure, whereas PV modules showing dendritic crack patterns have been probably exposed to heavy mechanical loads. Snail tracks can be found in a great variety of solar modules, but not in all. The combination of different materials (encapsulant and back sheets) with UV radiation and temperature plays an important role in the creation of snail tracks.				
	Production		Installatio	n 🔲	Operatio	on 🔲
Impact	Cell cracki any size th cell's area formance. area, the p snow clima mean degr risk of hot no influenc the isolatio	ng does not necess at does not, or likely from the electrical c Even if each cell in ower loss of the mo ate zones cell cracks radation rates of up spots and burn ma e on the performance n of cracked cell par	arily lead to y will not th ircuit can b a 60 cell m odule is typ s seem to l to 7%/y ca irks due to te of the PV ts may be a	o a failure of the rough its propage be considered to nodule is cracke bically below 2.5 have a more pro in be found. Bes in inactive cell pair accelerated more	e module. The pation, remove have limited t d, but do not l % of the nom nounced impa- sides the risk of ts. Snail trac e to the observ e than it would	presence of a crack of more than 10% of that o no impact on the per- ead to a separated cell inal power. In cold and act. Here relatively high of power loss there is a ks are reported to have red porous silver fingers be without snail tracks.
	Safety:			Performance:	12345	
Mitigation	Corrective	actions	Preventiv (recomme	e actions ended)	Prevent (optiona	l)
	Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules.Adequate transport proce- dures, installation and clean- ing by trained personal, in case of higher snow or hail modules.Request EL pictures from duction, pre-shipment or house inspection, EL in with mobile laboratory be during installation, regul inspection or after weather conditions.					t EL pictures from pro- pre-shipment or ware- nspection, EL images pile laboratory before or nstallation, regular EL on or after sever conditions.

EXAMPLES	(page1)				PV	FS 1-1vs.01
Examples 1-3						
	Cell chipping. A v is missing from cell, but does r lized region. [Kö	very small region the edge of the not enter metal- ntges14]	Large crack at c by eye - small p (<10%) is no lo connected. [Kön	cell corner visible ortion of the cell onger electrically tges14]	Cell crack with s lation of any ce gation could is >10%. [Köntges	snail track. No iso- Il part. The propa- olate a cell area 14]
Severity				H <mark>2</mark> 1		+2
Examples 4-6	Cell cracks visib bleaching effect. mistaken for sna	le by the photo- This may not be ail tracks. [Könt-	Two cell cracks delamination, Ev photo bleaching	s with extensive /A browning and	EL image of 2 isolates more th area ITUV Rhei	cell cracks which an 10% of the cell inland]
Severity	ges14]			-2245		
Examples 7-9	Snail track exam	ple. [Yang19]	Snail track exam	mple. [Yang19]	EL of cell cracks [Köntges14]	s with snail tracks.
Severity		H 2 3 4 H	(f) (e)	⊢ <u>234</u> ⊣		⊢234⊣

EXAMPLES	(page2)		PV	FS 1-1vs.01
Examples 10-12	Zoom of snail track with delami- nation. [Yang19]	Zoom of snail track with browned fingers. [Sinclair17]	Zoom of snail tra tion. [SUPSI]	ack with delamina-
Severity				⊢234⊣
Examples 13-15	Cell crack with EVA delamina-	Typical EL picture of a cell crack	Repetitive crack	pattern due to im-
	PVFS 1-3)	caused by hall. [100 Rheinland]	SUPSI]	iering machine.
Severity				⊢ <mark>2</mark> 1
Examples 16	Typical EL picture of cell cracks of mechanical load (X-crack patter [Köntges14]	caused by a heavy homogeneous n) also without glass breakage.		
Severity		⊢- <mark></mark>		

Component	Module		lent er b	- kehe et			PVFS 1-2 vs.01	
Delect	DISCOIO	uration of encapsu	liant or ba	acksneet				
Appearance	The degra to dark be cell interco mogeneo cally, for wide clea observed sheet (lay sulant dis over som lates with cells of th	to dark brown discolouration. Colour can be next to or above the cells, along the busbars or cell interconnects or on the back or front side of the backsheet. Often discolouration is inhomogeneous and follows spatial patterns depending on the type of module construction. Typically, for glass/backsheet modules the browning occurs in the central region of the cells with wide clear encapsulant areas, or "frames" around the cell edges. Discolouration can also be observed in the encapsulant between neighbouring solar cells when the front side of the backsheet (layer behind the cells) is degrading. For glass/glass module constructions the encapsulant discolouration is mostly spatially uniform, but can also show patterns of clearer areas over some cells. In glass/backsheet modules the location of these patterns generally correlates with cell cracks . In some cases, the discolouration is more pronounced in one or more cells of the module.						
Detection	VI, (IV, IF	RT)						
Origin	In the pa used enc proved st lizers. If t patterns of of oxyger interact w creates a single cel was at hig the cells	In the past, yellowing or browning was mostly associated with the degradation of the mostly used encapsulant ethylene vinyl acetate (EVA) but this problem was greatly solved by improved stabilisation of the polymer with additives, including UV absorbers and thermal stabilizers. If the choice of additives and/or their concentrations are inadequate, or the lamination process is inadequate or incomplete, the encapsulation material may discolour over time. The patterns of discolouration observed in the field can be very complex because of the diffusion of oxygen or the products of reaction, such as acetic acid, generated when heat and UV light interact with EVA. The presence of oxygen leads to the so called photobleaching effect which creates a ring of transparent EVA around the perimeter of a cell or a cell crack. The case of single cells which are far darker than the adjacent cells, implies that the most discoloured cell was at higher temperature than the surrounding cells, perhaps because of differences between the cells or the						
	Productio	n	Installatio	n 🗌		Operatio	on 🔲	
Impact	Discolora This type decrease dation rate moderate the cell, i concomit at a single EVA does tive back cracking	tion is a sign that the of degradation is pre- of module current an es due to yellowing an climates. While it is u t may correlate to: hig ant corrosion and em e cell, where it could of s not present any dire sheets that can resu of backsheet due to	e polymeric edominantl id power p re about 0. ncommon gh tempera ibrittlemen cause a sul ct safety is lt in a loss thermome	c compounds with y considered to roduction is dete 5%/a and may ro for EVA discolou atures in the field nt . Unless discol- bstring bypass-d sues. More critic s of mechanical echanical stresse	thin the fine ected. each uratio d, the ourat iode cal is propes.	he modu rst an ae Typicall up to 1% n to indu generat ion is ver to turn or the disco perties (e	le started to degrade. esthetic issue before a y, mean yearly degra- o/a in hot and humid or ce other failures within tion of acetic acid and y severe and localized n, the discolouration of blouration of UV sensi- elastic behaviour) and	
	Safety:			Performance:	1 2	2 3	-	
Mitigation	Correctiv	e actions	Preventiv (recomm	e actions ended)		Prevent (optiona	ive actions al)	
Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules.Check validity of certification and E				alidity of IEC 61 on and BOM.	215	Regular For area request test sta triple IE tion.	system inspections as with harsh climate, modules pass higher ndards, like double or C 61215 test condi-	

EXAMPLES	(page1)				PVF	S 1-2 vs.01	
Examples 1-3							
	Slightly browned EVA in the cen- tre of the cell with photobleaching at the edges. [Köntges14]		Slightly browned EVA in the cen- tre of the cell with photobleaching at the edges. [India18]		Yellowed backs side. [Sinclair17	Yellowed backsheet from the in- side. [Sinclair17]	
Severity		+2		-231		1 2	
Examples 4-6	Dark discolourat between cells a	ion at cell edges, nd over gridlines	Dark discolourar zation. [Sinclair1	tion over metali-	Backsheet air [Sinclair17]	side yellowing.	
	and busbars. [Si	inclair17]					
Examples 7	Single cell brow than the others of ing. [Köntges14]	ned much faster due to local heat-				1 2	
Severity		H 2 3 - + 1					

Component	Module				PVFS 1-3vs 01		
Defect	Front delamination				1 11 0 1 003.01		
Appearance	Any local separation of the layers between (i) the front glass and the encapsulant or (ii) the cell and the encapsulant, visible as bubbles or as bright, milky area/s. It may appear continuous or in spots. The position and size of the delamination or bubble depends on the origin and progress of the failure.						
Detection	VI, (INS)	√I, (INS)					
Origin	The adhesion between the glat mised for many reasons. Typic linking of EVA, too short lamina improper cleaning of the glass of the raw material) or enviro stresses, UV). Delamination is therefore more frequent and se	The adhesion between the glass, encapsulant, active layers, and back layers can be compro- mised for many reasons. Typically, it is caused by the manufacturing process (e.g. poor cross inking of EVA, too short lamination times, too high pressure in the laminator, contaminations, mproper cleaning of the glass, incompatibility of EVA with soldering flux, inadequate storage of the raw material) or environmental factors (e.g. thermal stresses, external mechanical stresses, UV). Delamination is generally followed by moisture ingress and corrosion . It is therefore more frequent and severe under hot and humid conditions.					
	Production	Production Installation Operation					
Impact	Delamination or bubbles do not automatically pose a safety issue, but they can result in re- duced insulation of the component and increased safety risk when they form a continuous path between electric circuit and the edge due to possible water ingress. Moisture in the mod- ule will decrease performance due to an increase of series resistance, affect long term relia- bility and in some cases also the structural integrity of the module. Moreover, delamination at interfaces in the optical path will result in additional optical reflection and subsequent decrease in current. This can be the origin of current mismatch. If the mismatch is significant, it will trigger the bypass diode and cause further power loss. The inverter might also shut down due to leakage current's leading to a further performance loss. Manufacturing related delamination issues often affects a relevant percentage of modules within the same production batch and consequentially has a big impact on system performance.						
	Safety:		Performance:	1234	2 3 4 5		
Mitigation	Corrective actions	Preventiv (recomme	e actions ended)	Prever (optior	ntive actions nal)		
	Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules. In case of in- dividual module testing all modules which failed the insu- lation and/or wet-leakage test should be replaced.	Check validity of IEC 61215 certification and BOM, ground fault detection by inverter or other devices at all time.		215 Extend und heat), r or tions (of EVA inspec	led testing (e.g. damp pre-shipment inspec- e.g. cross linking level () regular visual system tions.		

Examples 1-3	
Encapsulant delamination in un- critical position. [SUPSI] Encapsulant delamination from cell caused by production pro- cess. [SUPSI] Encapsulant delamination from cell along grid fingers and b bar. [Packard12]	nation from rs and bus
Severity	2
Examples 4-6 Final problem in the second se	nation near tion with cell
ard12] Severity	3 - 4 1
Examples 7-9 Delamination in front of cell in the centre of the module. [Moser17] Delamination at module insert connections of a glass/glass Delamination at cell edges. [Kö	dges. [Könt-
(see also FS 1-2) module (junction box). [SUPSI] Severity -2 3 4 -1	3 4 -1

EXAMPLES	(page2)				PVF	S 1-3 vs.01
Examples 10-12						
	Encapsulant de ders. [Sinclair1	elamination at bor- 7]	Encapsulant de a bus-bar in a module edge. [l	lamination along cell close to the Moser17]	Encapsulant dela glass (spotted c ture) at the edge clair17]	amination of from lue to glass tex- e of the cell. [Sin-
Severity	•	1	•	1 2	•	-231
Examples 13-15						
	Delamination c ous path betwe and the edge. [reating a continu- een electric circuit Moser17]	Delamination [Köntges17] (se	with corrosion. ee also FS1-11)	Delamination ca ment of backshe of encapsulant [SUPSI]	used by detach- eet with exposure from the back.
Severity	e	⊢ <mark>1 3 4 5</mark>	e	⊢ <mark></mark> 3 4 5	e	

Component Defect	Module Backsber	et delamination				P	VFS 1-4vs.01
Appearance	Any local backsheet tion). The worst case depend on	separation of the po and the rest of the r backsheet may app e, one or more layers the cause and prog	blymeric ba module, or ear wavy, v s may peel ression of	ick sheet layers within the multila with locally limite off. The position the failure.	leading ayer ba ed bump n and e	g to an air icksheet (= ps, bubble ixtent of the	gap between the internal delamina- s or ripples. In the e delamination will
Detection	VI, (INS)						
Origin	There are market. Wi layer) inter degradatio one or mo the backsh from a lack the delami from differ (material in UV and mo frequent an insufficient	There are many different forms and compositions of polymeric multilayer backsheets on the narket. With laminated backsheets (polymeric layers adhered to each other by a thin adhesive ayer) internal delamination can appear: the multiple layers may delaminate upon adhesive legradation, which may lead to local delamination of two subsequent layers or a peel-off of one or more layers. Co-extruded backsheet are prone to internal lamination. Delamination of he backsheet from the encapsulant can appear with all types of backsheets and originates rom a lack of adhesion between the backsheet are (i) thermo-mechanical stress originating rom differing CTE of the individual polymeric layers, (ii) chemical reactions at the interfaces material incompatibility) or deteriorated interfacial bonding as a result of the attack from heat, JV and moisture or (iii) external mechanical stress applied on the module. Therefore, it is more requent and severe under hot and humid conditions. Delamination can be also caused by an nsufficient lamination process e.g. too short lamination times.					
	Production Installation Operation						
Impact	If delamination occurs forming bubbles in a central, open area of the back, it will not pres an immediate safety issue. That area would likely operate at slightly higher temperatures the heat conduction/dissipation through the backsheet is disturbed. But as long as the bub is not further mechanically cracked or expanded, the performance and safety concerns minimal. However, if delamination of the backsheet occurs near a junction box, or near edge of a module there would be more serious safety concerns. Delamination at the edge n provide a direct pathway for liquid water to enter the module during a rainstorm, or in respon to the presence of dew. That can provide a direct electrical pathway to ground creating a v serious safety concern. Similarly, delamination near a junction box can cause its loosen putting mechanical stress on live components with the danger of breakage. A break mi cause a connection failure to a bypass diode and possibly result in an unmitigated arc at system voltage. In multilayer backsheets the severity depends also on which layer is affect						, it will not present er temperatures as long as the bubble afety concerns are n box, or near the on at the edge may orm, or in response and creating a very ause its loosening, ge. A break might nitigated arc at full h layer is affected.
	Safety:	f e e		Performance:	12	3 4 -	
Mitigation	Corrective	actions	Preventiv (recomme	e actions ended)	P (c	Preventive a optional)	actions
	Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules. In case of in- dividual module testing all modules which failed the insu- lation and/or wet-leakage test should be replaced.		Check validity of IEC 61215 certification and BOM. Ground fault detection by in- verter or other devices at all time.		215 R y in- it all	Regular sys	stem inspections.

EXAMPLES	(page1)				P\	/FS 1-4 vs.01
Examples 1-3						
	Multiple bubbles and edge of [Köntges16]	s in the centre the backsheet.	Blisters because rier, such as [Köntges17]	e of vapour bar- aluminium foil.	Big central bu ination. [Könt	bble + wavy delam- ges14]
Severity	e	⊢234 ⊣	e	1234	<u>e</u>	1
Examples 4-5						
	Backsheet delar rect exposure [SUPSI]	nination with di- of encapsulant.	Delamination of exposure of [SUPSI]	top layer without encapsulant.		
Severity		H 2 3 4 H		1 2 3		

Component Defect	Module Backsheet cracking				PVFS 1-5vs.01			
Appearance	Any damage of the backsheet (surface or whole stack) that is visible as crack, burst or scratch. The location and extent of the cracks depend on the cause and progression of the failure. The cracked area may be localized (e.g bursted bubble, scratch), extend along specific module areas (e.g. long or between the cells, along the busbars) or extend over large or the full area of the module (e.g embrittled surface). The crack can be very deep and affect the back sheet stack.							
Detection	VI, (INS)	VI, (INS)						
Origin	The degradation of the backsheet can be caused by environmental factors like UV-irradiation, nermal stress, external mechanical stress or by internal stress (e.g. thermomechanical stress with the multimaterial composite PV-module) or incorrect handling during transport and instal- ation (local cuts, scratches). Deep backsheet cracking (whole backsheet stack split) is often oblowed by moisture ingress and corrosion . This is more frequent and severe under hot and numid conditions. The use of low quality material (e.g. low UV resistance) or incompatible naterial combinations (backsheet ↔ encapsulant) causes most of the premature degradation ailures. Discolouration and or strong chalking can be precursors for backsheet cracking. Deep cracks or bursted bubbles can be the result of local hotspots/burn marks that split or preak the backsheet.							
	Production	Installatio	n 🔲	Opera	tion			
Impact	A broken backsheet can caus potential ground fault. On the lo into the module which induces case of deep cracks reaching promised and safety is not any	e electric ong-term, p further fail the active more fulfill	al insulation fail ower degradation ures (e.g. corrosi part of the cells, ed.	ure, posing n due to the on, delamin the insulati	a safety hazard and a penetration of moisture ation) can occur. In the on is immediately com-			
	Safety:		Performance:	1234	5			
Mitigation	Corrective actions	Preventiv (recomm	e actions ended)	Prever (optior	ntive actions nal)			
	Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules. In case of in- dividual module testing all modules which failed the insu- lation and/or wet-leakage test should be replaced.	lirect safety of 5 should gular inspec- one to moni- the not re- in case of in- testing all iled the insu- leakage test of.						

EXAMPLES	(page1)				PVF	S 1-5vs.01
Examples 1-3						
	Cracked backsh tion with yellow cell. [Eder19]	eet in combina- ing under a hot	Squared cracks terspaces. [Eder	beneath cell in- 19]	Cracking betwe ard12]	en cells. [Pack-
Severity	f m e	⊢2345	f m e	⊢ <mark>2345</mark>	f m e	⊢2345
Examples 4-6	Longitudinal cra der bus bars. [Ed	ucks located un- der19]	Backsheet crack	ing. [DuPont20]	Backsheet [DuPont20]	cracking.
Severity	f m e	⊢ <u>2345</u>	(f) (m) (e)	⊢2345	(f) (m) (e)	⊢2345
Examples 7-8	Localized supe [Köntges17]	erficial damage.	Deep scratch on Rheinland]	backsheet. [TUV		
Severity	f e m	1	(m (e	1 2		