

Component			PVFS 1-16 vs.01						
Defect	Not conform power	rating							
Appearance	The STC output power of a brand new module is below a specified tolerance limit or the min- imum nameplate output power is not clearly specified by the manufacturer.								
Detection	IV, (MON)								
Origin	Deviations of the measured power of a single module respect to the name plate power depends on the product variability, manufacturing quality, the labelling policy and the measurement uncertainty. The quality of cells (e.g. LID susceptibility) together with the binning method applied in production for the reduction of mismatch losses, has a significant impact on the product variability. The deviations in the measurement in the factory comes from several sources of uncertainty, for example the environment temperature, measured module temperature, calibration of the solar simulation, maintenance of the reference module, measurement equipment, connectors and cables. According to the international standards, the power rating has to take into account any technology related initial degradation effects (for c-Si see FS 1-17). This means that after a first exposure to light the output power of a new module has still to be within the rated power tolerance. The measurement uncertainty of the test laboratory performing the STC performance test has therefore to be taken into account. The modules have to be stabilised according the procedure described in IEC 61215-2:2021. Technology specific test requirements are described in IEC 61215-1-1:2021 to IEC 61215-1-4:2021. Depending on the technology, a maximum allowable measurement uncertainty is defined for the verification of power ratings. For c-Si modules it is specified as 3%. A PV module is considered to be conform to the IEC61215 standard, when following criterion (gate 1) is fulfilled:								
	P _{max}	$(\text{Lab}) \cdot \left(1 + \frac{\frac{1.65}{2}}{2}\right)$	$\frac{ \mathbf{m}_1 [\%]}{100} \ge P_{\max}($	(NP) $\cdot \left(1 - \frac{1}{2}\right)$	$\frac{ \mathbf{t}_1 [\%]}{100}\right)$				
	P_{max} (Lab): measured maxir P_{max} (NP): minimum rated		each module in stabiliz each module without		on tolerances				
	m_1 : measurement u	ncertainty in % of lal	poratory for <i>P_{max}</i> (expa	anded combine	ed uncertainty (k = 2)				
	t_1 : manufacturer's rated lower production tolerance in % for P_{max}								
	The minimum nameplate power rating, $P_{max}(NP)$ and tolerance t_1 has to be derived from the nameplate or data sheet values. If the $P_{max}(NP)$ derived from the datasheet is different from the nameplate value, the module can be considered to be not conform. If the tolerance is not stated on the nameplate or the datasheet, then $t_1 = 0$. If the tolerance is not reduced to a single value on the nameplate or data sheet (for example, if multiple tolerances or measurement uncertainty components are specified) the smallest number shall be utilized.								
	Production	Installat	on 🗌	Opera	ation				
Impact	A non-conform STC power rating is not a real module failure, as it causes no degradation or safety issue, but it has a negative impact on the lifetime energy yield and financial return. An incorrect estimation of the installed STC power has a direct impact on the energy yield predictions and investor expectations.								
	Safety:		Performance:	1 2 3					
Mitigation	Corrective actions		Preventive actions (recommended)		Preventive actions (optional)				
	Confirm underperfor through an accredited F laboratory. Claim for n power.	PV test data sh	ower warranties eet conformity, nodules from trus cturers.	pur- ing of sted and/o ture of	Independent third party test- ing of samples at factory gate and/or arrival on site. Signa- ture of a contractual agree- ments.				





Component Defect	Module Light induced degradatior)) PVFS 1-17 vs.01							
Appearance	Light induced degradation in crystalline silicon modules is recognisable mainly as a drop in STC output power, but also short circuit current and open circuit voltage, within the initial life- time of a PV system. It isn't correlated with any visual defect or other failure modes. Increasing non-uniformity of electroluminescence images (patchwork pattern) can in some cases high- light an ongoing degradation process.								
Detection	IV, (EL, IRT)								
Origin	Two different light induced degradation effects are known: LID (light induced degradation) and LeTID (light and elevated temperature induced degradation). Both degradation modes occur at cell level, but the physical mechanism staying behind them are different. The first is related to the concentration of boron and oxygen in the cells, whereas the second one is probably correlated to the concentration of hydrogen in the cell, but the mechanisms are still not fully understood. Mainly p-type multi and mono crystalline silicon modules are affected. High-efficiency cell technologies that use n-type wafers, such as n-type PERC, HJT, or n-PERT seem to be much less or not at all concerned by these two degradation effects. LID occurs only within the first days of exposure to the sun and is limited to 1-3%, whereas LeTID is in a more severe and long-term light induced degradation mechanism. LeTID was observed for the first time with the introduction of PERC modules on the market. The degradation can reach up to 10% and sum-up with the LID loss. It occurs only at elevated temperatures above 50 °C. The speed with which the degradation occurs depends on the average module temperature and is therefore strongly site dependent. The time frame in which it occurs is in the order of magnitude of years. Once the full degradation is reached the modules can regenerate, recovering the lost power. This process is however very slow and also climate dependent. The lost power may even not recover over the typically expected 25-year lifetime of a module. There exist approaches of accelerated regeneration of LeTID-sensitive modules in the field, but they are not very user-friendly. Over the last years always more manufacturers adapted their cell production of LeTID and depending on the methodology the degradation rates, even if reduced, can differ from one manufacturer to the other and range from 1-4%.								
	Production	Installation	Operation						
Impact	LID or LETID causes no safety problems, but it has a negative impact on the lifetime energy yield and financial return. An under-estimation of the initial degradation has a direct impact on the energy yield predictions and investor expectations. LID is less critical for the investors, because it is generally less severe and it is taken into account by the manufacturers when labelling the modules and defining the first year warranty, whereas a high LeTID degradation rate and the difficulty to predict the trend over time is much more critical for manufacturers' warranties and system owners. The sensitivity of PV modules to LeTID can be tested in the laboratory. Serious LID above 10% degradation may result in hotspot and can be detected by IR camera, it happened mainly to the cells produced when PERC were just commercialized and no mitigation of LID in the manufacturing process was available.								
	Safety:	Performance: H	3						
Mitigation	Corrective actions	Preventive actions (recom- mended)	Preventive actions (op- tional)						
	Confirm underperformance through an accredited PV test laboratory. Claim for missing power.	Verify power warranties. Ver- ify the use of LeTID stable cells by module manufacturer.	Request test reports with % power loss for realistic estima- tions. Stipulate a contractual agreement on tolerated loss. Test individual modules. Ver- ify BOM (cell type).						

Component	Module PVFS 1-18vs.01							
Defect	Insulation failure				FVF5 1-10VS.01			
Appearance	A module with bad insulation between its current carrying parts and the frame (or the outside world) are not directly visible by eye. An unequivocally detection is only possible through a measurement of the insulation resistance of the module under dry (≥40 Mohm/m ²) or better humid/wet conditions. It can be sometimes deduced by the presence of visual defects which can potentially lead to insulation problems. Under certain circumstances like after a rain fall or in the early morning when the PV modules are covered by dew, this kind of defect is detected by the inverter (low insulation fault) or the inverter is switching off when the resistance value falls below a certain limit.							
Detection	INS, (MON)							
Origin	module, due to solar cells too the use of inadequate encapsu the installation phase it can be operational phase it is general cess close to the edge of the Modules with failed or skipped surance could be also the orig	Insulation failures can have different causes. It can occur in the design/production phase of a module, due to solar cells too closely positioned to the frame or to material weaknesses like the use of inadequate encapsulation or backsheet materials or a poor lamination process. In the installation phase it can be caused by mechanical damages of the module, whereas in the operational phase it is generally caused by catastrophic events or due to a delamination process close to the edge of the module or water ingress or condensation in the junction box. Modules with failed or skipped insulation test in production due to an insufficient quality assurance could be also the origin of the problem. Various module failures are at the origin of an insulation failure: backsheet and encapsulant delamination, backsheet damages, burn marks, glass breakage						
	Production	Installatio	n 🔲	Opera	ation			
Impact	A low insulation resistance at module level itself does not lead to a performance loss, until an inverter failure occurs. The presence of an electrical leakage current to the frame can become a safety hazard exposing persons to a potential electric shock hazard. Touching non-insulated parts of the string or frame can cause severe injury, without the use of safety gear and safe measuring instruments.							
	Safety:		Performance:	1234	5			
Mitigation	Corrective actions	Preve (optio	entive actions nal)					
	Modules with a direct safety risk or a severity of 5 should be replaced. Regular inspec- tions should be done to moni- tor the status of the not re- placed modules. In case of in- dividual module testing all modules which failed the insu- lation and/or wet-leakage test should be replaced.	certification missioning IRT, grou	validity of IEC 61215 ation and BOM, com- ning of system with round fault detection by r or other devices at all		lar system inspections, ation testing of modules nobile test centre before lation.			

Component	Module		PVFS 1-19 vs.01					
Defect	Hot-spot	(thermal patterns	;)			FVF3 1-19 VS.01		
Appearance	A hot-spot is a thermal abnormality such as a local overheating or a thermal pattern which deviates from the normal behaviour of a module. It can be detected only by imaging techniques such as e.g. infrared thermography. Hot spots are not visible by the naked eye until they lead to irreversible hot-spot damages like e.g. local yellowing, burn marks, glass or cell break-age . The position, size, intensity and pattern of the hot-spot/s depends on the origin and progress of the failure, but also under which conditions the module is operating (shading, load and irradiance level). A temperature gradient of smaller than 10 K is considered as normal and is not a hot spot or thermal abnormality.							
Detection	IRT, (VI)							
Origin	crack and der joints, production reverse bia is high eno of solder, of the effects	A hot spot may be caused by shading, soiling, severe cell mismatch, damaged cells (e.g. cell crack and shunted cells), glass breakage, poor electrical connections (e.g. bad or broken solder joints, short circuits, cell interconnect ribbon failures), or low quality solar cell or module production. When such a condition occurs, the affected cell or group of cells is forced into reverse bias and will dissipate power, which can cause overheating. If the power dissipation is high enough or localised enough, the reverse biased cell(s) can overheat resulting in melting of solder, deterioration of the encapsulant and/or backsheet and glass breakage. To reduce the effects of hot spots bypass diodes are connected in parallel to the cells. Well-dimensioned and correctly working bypass diodes helps in reducing hot spot damages from occurring.						
	Production		Installatio	n 📃	O	peration		
Impact	Hot-spots do not always lead to a power loss. Due to normal tolerances in cell sorting and module production, thermal abnormalities of less than 10% of the recorded modules usually do not indicate a special quality issue. Most of the times modules with a single hot cell have an insignificant power loss. Power reduction becomes significant when a permanently activated bypass diode leads to a minimized power output of the affected solar cell string and thus to a reduction of the total module power output. The impact on system level is only visible when more modules are affected. Very high losses can occur when PID is the origin of the warmer cells. Module safety is affected when the overheating causes critical module damages or when it leads to a fire. A temperature gradient in a range of 10 K to 20 K is considered as unproblematic if it is not increasing during the operation of the PV power plant. Temperature gradients above 20 K are expected to cause power losses; in extreme cases, the material compound may even degrade, resulting in a safety issue during maintenance work. Further increase in temperature gradient are expected during the operation phase of the PV power plant if the modules are not replaced. If PV modules of a system are not cleaned and maintained at a suitable frequency, high temperatures of some cells or modules may occur due to bird droppings or power mismatch for a long time which may lead to module damage. At a later stage it might be difficult to evaluate whether the damage was caused by quality problems or by missing cleaning or maintenance procedures.							
	Safety:			Performance:	1 2	3 4 5		
Mitigation	Corrective	actions	Preventiv (recomm			reventive actions ptional)		
Modules with a direct safety risk or a severity of 5 should be replaced or repaired. I more than 10% modules show thermal abnormalities, the reason for that behaviou should be evaluated and re spective corrective actions should be implemented.			Commiss with IRT.	ioning of sys	stem R	egular system inspections.		

EXAMPLES (page1)

PVFS 1-19vs.01

Pattern	Description	Origin	Performance	Remarks	Safety	Power
	One module warmer than others			Check wiring		⊢ <u>·</u> · · · 5
	One row (sub- string) is warmer than other rows in the module		•	May have burned spot at the module		⊢ · · · 5
	Single cells are warmer, not any pattern (patchwork pattern) is recog- nized			Check wiring		(see PVFS 1-15)
	0	degradation	and <i>FF</i> redu-	grounding conditions - recovery	•	⊢ 2 3 4 5 (see PVFS 1-10)
	One cell clearly warmer than the others	effects - Defect cell	Power decrease not necessarily permanent, e.g. shadowing leaf or lichen	needed, cleaning (cell mismatch) or		1 2 3 4 5 (see also PVFS 1- 1, 1-3, 3-3)
	Part of a cell is warmer	 Broken cell Disconnected string interconnect 	Drastic power reduction, <i>FF</i> reduction			⊢ 2 3 4 5 (see also PVFS 1- 1, 1-7, 1-9)
	Pointed heating	 Artifact Partly shadowed, e.g. bird drop- ping, lightning protection rod 		Crack detection after detailed vis- ual inspection of the cell possible		← 2 3 4 5 (see also PVFS 1- 1, 1-7, 1-9)
dashed: shaded area	Sub-string part re- markably hotter than others when equally shaded	missing or	power reduction when part of this	May cause severe fire hazard when hot spot is in this sub-string		← 2 3 4 5 (see also PVFS 1- 15, 3-3)

Overview of typical IR image patterns observed in outdoor measuerments. [Köntges14]

Component	Module	PVFS 1-20vs.01						
Defect	Soiling					F VI S 1-2005.01		
Appearance	Soiling is visible as a deposition of dust, dirt or other contaminants on the surface of a PV module. The deposition can be uniform or non-uniform and vary in thickness. Due to the presence of hot-spots caused by non-uniform soiling, it can be also seen through IRT imaging.							
Detection	VI, (IRT, MON)							
Origin	Soiling of PV modules can have various origins such as dust accumulation, air pollution, bird droppings or growth of moss, lichens or algae. It can be due to natural sources, as sand in desert areas, seasonal pollen or volcanic emissions, or due to human activities, as near min- ing, industry, high ways, railways, urban or agricultural surroundings. The soiling level and its persistence over time depends on the exposure time, the chemical composition and particle size as well as the local climate conditions. Whereas rainfalls and wind can lead to a natural cleaning of modules, humidity can have a contrary effect by increasing adhesion and cemen- tation of dust on the module. The module design (e.g glass coating, frame, distance of cells from the edge), the orientation (e.g tilt angle, azimuth, landscape/portrait) and mounting con- ditions (e.g clamps, height above ground, stringing) of the modules plays an important role. Typically soiling increases as tilt angles decreases. The direction of the wind or obstacles can influence the soiling process, leading to non-uniform patterns on system and module level.							
	Production		Installat	ion 🔲	Op	eration		
Impact	The deposited soiling layer causes optical losses, reducing the amount of light that reaches the solar cells, with a consequential performance drop. Soiling is not a real module failure, as it is reversible when the module is cleaned, but it has a negative impact on the lifetime energy yield and financial return. Soiling is a site-specific issue. In arid regions with seasonal dry periods and dust, extreme soiling losses of up to 25%/a are reported, if modules are not cleaned. In temperate regions with year-round rain, the annual soiling losses typically ranges between 0% to 4%. In case of specific soiling sources (e.g. railway, farming, etc.) and/or constraints of the natural cleaning effect due to unfavourable mounting conditions (e.g low tilt angle) much higher losses can be observed. Non-uniform soiling leads to current mismatch losses which further increases the power loss and to hot-spots which in extreme cases can permanently damage a PV module. In modules affected by potential induced degradation (PID), soiling can further accelerate the ongoing degradation effect. Soiling can be mitigated by cleaning the modules or preventing excessive soiling. The cleaning approach has to be appropriate to the type of soiling and site specific conditions (e.g. accessibility and water availability). The cleaning schedule should take into account that natural agents, such as rain-falls, wind or dew can have a natural cleaning effect at no cost. Anti-soiling coatings (ASC) can help in reducing soiling and stretch the cleaning frequency, but only if the coating is adequate for the type of soiling present on the system and if adequate cleaning processes are followed, which do not damage the coating. Moreover, it has to be considered that some ASC can also increase transmission losses by themselves.							
Mitigation	Safety: Performance: 2 3 4 5 Corrective actions Preventive actions Preventive actions							
		tional)						
	recommended when the reve- nue lost because of the missed energy production is higher than for the implementation of s					imation or measurement of ing losses prior to installa- n. Installation of soiling sen- s to determine the most fitable time to clean.		

EXAMPLES	6 (page1)				PVFS	1-20 vs.01	
Examples 1-3							
		soiling, which in s is self-cleaning	Uniform heavy s rail way station.	oiling caused by [SUPSI]	Non-uniform soiling caused by low inclination and close mount- ing to roof. [SUPSI]		
Severity		⊢ <mark>2</mark> 1		<u>⊢3</u> 4 –-1		H 2 3	
Examples 4-6							
		on the edge of a ed with edge soil-]			Soiling pattern demonstrating dominant wind direction on a test site in Atacama desert. [ISE]		
Severity		⊢ <u>23</u> 1		<u>⊢3</u> 41		<u>⊢+</u> 34-1	
Examples 7	Heavy biofilm ges16]	soiling. [Könt-					
Severity		4 5					